



18. Test and adjustments**WSAH8060 / WMAH100 / K8060 / VM100**

- Use a 2 x 25 to 30Vac / 100 - 120VA transformer.
- Connect the transformer to the AC power connections of the PCB.
- The Velleman transformer colour scheme is specified on the pcb.

☞ **Careful : Other brands may feature a different scheme !**

Y: yellow, R: red, B: blue, G: grey.

**Transformer supplied by ESR Electronic Components Ltd**ESR Order Code: **325-030**Model: **VTX-146-120-230**

Cross reference chart for transformer wiring

K8060 Board Ref	Velleman Colour	ESR Colour	Output Voltage
Y AC	Yellow	Yellow	30Vac #1
R AC-0	Red	Orange	0Vac #1
B AC	Blue	Black	30Vac #2
G AC-0	Grey	Red	0Vac #2